

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 24
Section: 19

Township: 10 North
Township: 10 North

Range: 2 West
Range: 1 West

Corner ID: Be Bl Y-13
Corner ID: Wash A-13


Monument Description & Remarks: Found 1" (o.d.) Iron Pipe at NE corner of section. Iron Pipe was flush with ground and 2.5" north of another 1" iron pipe which was 1.3' out of ground. Field checked with Mike Mundy, R.L.S. (1/17/98).

References on file in the County Surveyor's Office: Mike Mundy survey dated May, 1995.

RECOVERY TIE DRAWING

Field Book 97-03 Page No. 37

USGS Modesto Quad



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-2-2 of the Indiana Code; and the above data is given under my hand and seal this 16th day of October, 1997.

Kevin P. Enright
SEAL
MONROE COUNTY INDIANA
Administered by: Surveyor Review Board SEAL
SEAL
MONROE COUNTY INDIANA